

ABSTRACT OF THE DISCLOSURE

A method for coating photoresist (300) on a substrate (100) includes the steps of forming grooves (120) on the substrate, applying photoresist onto the substrate, and finally vibrating the substrate. The photoresist can be coated on the substrate evenly, and the efficiency of utilization of the photoresist is high.